

## W5300 Errata Sheet

Document History

Ver 1.1.0 (AUG. 19, 2008)	First release (erratum 1, 2, 3)
Ver 1.2.0 (FEB. 23, 2012)	Add Erratum 4, 5
	Change the Errata sheet form
	(Match with W3150A+ / W5100 Errata sheet.)
Ver 1.2.1(MAR. 23, 2012)	Add a solution for erratum 4,5

W5300 Errata Sheet

© 2012 WIZnet Co., Inc. All Rights Reserved. For more information, visit our website at <u>http://www.wiznet.co.kr</u>



Erratum 1			
Phenomenon	In TCP Mode, Sn_SSR(Socket status register)value does not change		
	from "0x10" or "0x11" during the TCP connection process.		
Condition	When the user executes "SEND" command, the user should stay in a		
	waiting state until it receives "SEND_OK" interrupt message <sup>1</sup> . However, when		
	the user executes "CLOSE" or "DISCONNECT" command to terminate the		
	connection during this waiting state, TCP Connection Establishment fails for		
	Socket status register(Sn_SSR)'s fixed value from "0x10" or "0x11".		
	Insert the following code when the connection is shut manually before the		
	completion of data transfer (or must insert the following code in CLOSE()		
	function)		
	socket(ch, Sn_MR_UDP, 5000, 0x00);		
Solution &	// Open with UDP. Port Number can be assigned randomly.		
Recommendat	sendto(ch, data_buf, 1,(uchar*)&destip,destport);		
ion	// Run the transmission command. destip and destport may use random value.		
	// Execute the test by setting destip at 0.0.01 desport 5000		
	close(ch);		
	// close		
	This will release the data transmission process from pending state.		
incomplete data	it takes some time to resolve this incomplete process. TCP would be in an a transmission process state when the destination window size is smaller than eing transmitted. Then TCP stays in a pending state until the receiver's window arge enough.		



Erratum 2	Erratum 2		
Phenomenon	In TCP Mode,		
	Decrease in transmission speed due to the absence of "Window Update		
	ACK" packet.		
Condition	Usually, TCP controls data transmission speed by exchanging the data buffer		
	size (window). The TCP will be in a pending state when the Peer's buffer size		
	is smaller than the data size being transmitted. Then the peer should		
	announce the change in data buffer size ("Window Update ACK" packet) so		
	that pending state could get released.		
	However, since W5300 does not automatically send out "Window Update		
	ACK" packet as above, user may experience decreased data transmission		
	speed.		
	*) For the reference, when W5300 performs in TCP mode, ACK packet will		
	be transmitted due to the "SEND" command and timeout. Moreover, if user		
	enables "No delayed option" and receives data packet from its Peer, then the		
	ACK packet will be transmitted as well.		
Solution & Recommendat	The most efficient way of solving this matter is to sustain the receiving		
	buffer size bigger than the MSS value as soon as possible. This is because		
	"Windows Update ACK" function is not necessary for above case.		
	If the condition doesn't get satisfied, then the User must execute "SEND"		
	command to transmit the "Window Update ACK" packet manually <sup>2</sup> followed		
ion	by variation of receiving buffer size: receiving buffer size is less than MSS		
	value -> "RECV" command enlarges the buffer size -> buffer size is sufficient		
	enough to hold the transmitted data.		

 $\frac{1}{2}$  Transmit the dummy data as a meaning of "No Operation" in user application.



Erratum 3			
Phenomenon	In TCP Mode,		
	Unable to read Destination Port Number Register (Sn_DPOR		
	correctly.		
Condition	After the TCP Connection Establishment, Destination Port Number Register		
	(Sn_DPORTR) stores correct Destination Port Number. But the user is unable		
	to read the Destination Port Number Register (Sn_DPORTR) correctly. For		
	example, register will store the destination port number, 0x1234 as it is.		
	However, user can only see duplicated high byte of port number, which is		
	0x1212.		
Solution & Recommendat ion	None.		
	However, since the Destination Port Number Register (Sn_DPORTR) contains		
	correct Destination Port Number, TCP function will perform without any		
	problem.		



Phenomenon	The W5300 replies with gate	eway IP address for the ARP request from
	normal node which has "0.0.	0.0" IP address. But normally the W5300
	should replies with target IF	address "0.0.0.0" not the gateway IF
	address.	
Condition	Normal Node+ IP: 0.0.0.0+ SN: 255.255.255.0+ Wrong	ARP Requester UP: 192.168.1.24 Target IP address: 192.168.1.254 ly m ust be 0.0.0.04 GW: 192.168.1.254
	misunderstands the node loca	um is subnet calculating logic. The W5300 ates other sub-network when target has V5300 set the target IP to the gateway IF
	instead of "0.0.0.0" and sends the	ne ARP reply.
	except two cases which are command in UDP. Because only mask register and sending the AF So set the subnet mask register right subnet mask value to the g When you use connect comman	er to "0.0.0.0" and keeping it but save the lobal variable when you initialize the W5300 id in TCP or send command in UDP, set the
	subnet mask register to the rig	nt value using the variable before executing
Solution &	connect or send command. Afte	r done connect or send command, clears the
Recommendat	subnet mask register again to ke	ep its value to "0.0.0.0"
ion	Before Applying (without solution)	After Applying (with solution)
	W5300 Initialization	W5300 Initialization
	Set GW: 192.168.1.254 Set IP: 192.168.1.2 Set SN: 255.255.255.0	Set GW: 192.168.1.254 Set IP: 192.168.1.2 Set SN: 0.0.0 & save the SN to global variable.
		<u> </u>
		TCP Connect         UDP Send           Set SN from global variable         "Execute connect command"           "Execute connect command"         "Execute send command"           (Clear SN : 0.0.0)         (Clear SN : 0.0.0.0)

© Copyright 2012 WIZnet Co., Inc. All rights reserved.

5/8



Example pseudo code:

/\* Global variable declaration for subnet mask value \*/

unsigned char subnet\_val[4];

/\* W5300 initialization function \*/

Function Initialize\_W5300( )

```
/* Clear the subnet mask register */
```

IINCHIP\_WRITE(SUBR0, 0);

IINCHIP\_WRITE(SUBR1, 0);

```
IINCHIP_WRITE(SUBR2, 0);
```

IINCHIP\_WRITE(SUBR3, 0);

/\* Save the right subnet mask value if the subnet is 255.255.255.0 \*/

subnet\_val[0] = 255;

subnet\_val[1] = 255;

subnet\_val[2] = 255;

```
subnet_val[3] = 0;
```

/\* TCP connect function \*/ *Function TCP\_Connect(* )

/\* Set the subnet mask register to the right value using the variable \*/
IINCHIP\_WRITE(SUBR0, subnet\_val[0]);
IINCHIP\_WRITE(SUBR1, subnet\_val[1]);

```
IINCHIP_WRITE(SUBR2, subnet_val[2]);
```

IINCHIP\_WRITE(SUBR3, subnet\_val[3]);

- '\* Execute TCP connect command \*/
  IINCHIP\_WRITE(Sn\_CR(socket), Sn\_CR\_CONNECT);
- /\* Wait for command done \*/
- while(Sn\_CR(socket));
- /\* Clear the subnet mask register again and keep it \*/

IINCHIP\_WRITE(SUBR0, 0);

IINCHIP\_WRITE(SUBR1, 0);

W5300 Errata Sheet







Erratum 5	
Phenomenon	Assuming that the IP address of W5300 is "0.0.0.0" and the gateway, subnet mask is valid (not "0.0.0.0"), the W5300 set the target IP address of ARP request to the gateway IP address not the target node IP address when sends ARP request to another node. So the peer node cannot receive the ARP request from the W5300.
Condition	Normal Node+/ IP: 192.168.1.3+/ SN: 255.255.0+/ GW: 192.168.1.254+/ARP Request with+/ Wrong Target IP address: 192.168.1.254+/ Norm ally m ust be 192.168.1.3+/ GW: 192.168.1.254+/IP: 0.0.0+/ SN: 255.255.0+/ GW: 192.168.1.254+/The W5300 miss calculates the sub-network location when sends the ARP request if its own IP address is "0.0.0.0". In the same condition, even if the gateway IP address is "0.0.0.0", the W5300 sends ARP request to "0.0.0.0" IP address because the W5300 sends ARP request to the gateway.
Solution & Recommendat ion	The reason of this erratum5 is same as erratum4 so the solution is also same with erratum4. Please refer to the solution of erratum4.